0-100mbar (0-10kPa) Pressure Sensor

Standard Range	Pressure Type: Gauge Pressure	
	Pressure Range: mBar / kPa	0-100 / 0-10
Technical Index	Signal Output:	0 ~ 5VDC
	Signal Line:	3 Wire
	Supply Voltage:	9~30VDC
	Accuracy:	± 0.5% FS
	Zero Drift:	± 0.02% FS/°C
	Thermal Sensitivity Shift:	± 0.02% FS/°C
	Long-term Stability (1 Year):	± 0.01% FS
	Frequency Response (-3dB):	3.2kHz
	Compensated Temperature:	-20 ~ +85°C
	Working Temperature:	-40 ~ +70°C
	Storage Temperature:	-40 ~ +70°C
	Overload Pressure:	300% FS
	Burst Pressure:	500% FS
	Mechanical Vibration:	± 20g
	Impact (11ms):	100g
	Environmental Protection:	IP65
	Pressure Connection:	BSPP ¼
	Material:	17-4P ST/STL
	Approval	CE, RoHS
Body Size	**************************************	
Electrical Connection	Red: Vcc to Merlin Panel [+] Black: GND to Merlin Panel [-] Blue: +Out to Merlin Panel [IN] Bare: Shield	

Oceania Gas Safety

Tuakau, Waikato New Zealand +64212386990



ww.oceaniagassafety.com

Information on waste disposal for consumers of electrical & electronic equipment.

When this product has reached the end of its life, it must be treated as Waste Electrical & Electronics Equipment (WEEE). Any WEEE marked products must not be mixed with general household waste, but kept separate for the treatment, recovery and recycling of the materials used. Please contact your supplier or local authority for details of recycling schemes in your area. Alternatively, S&S Northern products can be securely packaged and returned clearly marked for disposal.

